



### Features:

- High quality connectors
- Low cost
- Reliable
- Off the shelf

## About

Plug into Multimeter to give resistance on testing. Provides a 20K $\Omega$  or 100K $\Omega$  shunt load to help reduce noise.

## Technical Data

Panel Indicators	
Normal	Battery Voltage above threshold
Low	Battery Voltage below thresho
Adjust	Adjusting threshold voltage

Part Number	
XP3513 1000	20K $\Omega$ Shunt
XP3514 1000	100K $\Omega$ Shunt